



2018 CAT  
307E2  
TRACK EXCAVATORS

INSPECTION DETAILS

Inspection Type	Marketing
Inspection Form	Standard
Inspection #	10088071
Inspection Status	Completed
Created	12/27/23 11:04:32
Updated	01/19/24 14:29:53
Created By	Mcloughlin, Calum A.
Inspector	Ruggles, John A.
Salesperson	Armstrong, Larry
Stock #	UP15908
Serial #	KC901088
SMU / Hours	1,534
Location	Austell, GA 30168, United States



CLIENT DETAILS

Name	
Company	
Address	
City	
State	
Country	
Postal Code	
Email	Larry_armstrong@yanceybros.com
Phone	

FEATURES

General

- Auxiliary Hydraulics Pressure
- Lighting
- Radio
- Engine Enclosures
- Mirrors
- Hand and Foot Control
- Product Link

Emissions

- EPA Label
- Ultra Low Sulfur Diesel Fuel

Technology

- Pilot Control

CONDITION

Good

Fair

Poor

Approved Repair

GENERAL APPEARANCE


Catwalk		Counterweight		Crankcase Guard / Battery Box	
Decals		3Eng. Enclose Hood / Stack		Engine Doors	
Fenders		Fuel Tank		Grab Irons	
Hood		Main Frame Welds		Paint	
Plastic		Radiator Grill & Shroud		Sheet Metal	
Steps / Ladder					
Cleaning Required		Extra Fuel Tanks		S.O.S. Taken	
NO		NO		NO	


SAFETY ITEMS

Brake Hold		Horn		Swing Brake	
ROPS		Safety Decals In Place		Safety Decals Legible	
YES		YES		YES	

GAUGES, OPERATOR STATION, CONSOLE

Air Conditioner		Dash Console		Door Latches	


EMS Panel / Warnings  


Floor Boards  


Gauges  


Glass/Mirrors  



Heater  


Interior Lights  



Meter  


Product Link  


Seat Belt  


Seat Cushion / Arm Rest  


Switches  


Windshield Wipers  



Back Up Alarm  
**YES**


ROPS Certification Plate  
**YES**


**ENGINE**

Air Cleaners  



Belts / Pulleys  



Engine Supports  


Exhaust / Muffler  


Fuel Injection System  


Governor  


Operating Condition - ENGINE  


Turbocharger / Blower  


Blow By  
**NO**

Compression in Radiator  
**NO**

Emissions Decal  
**YES**

Fluid Levels OK?  
**YES**

Knocking  
**NO**

Oil Leaks  
**NO**

Water in Oil  
**NO**


**COOLING SYSTEM**

Coolers  


Fan  


Fan Drive  



Hoses  


Radiator  


Water Pump  


**ELECTRICAL, STARTING AND CHARGING SYSTEM**

Alternator  


Batteries / Cables  


Lighting  


Starter  


Wiring  



Block Heater  
**NO**

Ether Aid  
**NO**

**HYDRAULICS**

Boom Cylinder  



Bucket Cylinder  


Control Linkage  


Hose Lines  


Operating Condition -  
HYDRAULICS  


Pump Drive  



Pumps & Valves  


Stick Cylinder  


Swing Gear  


Swing Motors  



Tank  


Travel Motors  



**BOOM**

Boom Condition  


Boom Pins  


Pins & Bushings - BOOM  


**STICK**

Pins & Bushings - STICK  


Stick Conditions  


Stick Pins  


**BUCKET**

Bucket Bottom  
●●●

Bucket Linkage  
●●●

Bucket Mounts  
●●●

Bucket Sides  
●●●

Teeth / Adapters  
●●●

Quick Coupler  
**NO**

---

**UNDERCARRIAGE**

Track Frame - Left  
●●●

Track Frame - Right  
●●●

---

**FINAL DRIVES**

Housings  
●●●

Planetaries / Diff  
●●●

MARKETING PHOTOS (26)

















LINE ITEM PHOTOS (3)

Decals  
●●●



TRADE WORKSHEET		Mcloughlin, Calum A.	
ASKING PRICE			USD
TARGET SELLING PRICE			
MARGIN / MARKUP		0.0	%
REPAIR CHARGES SUBTOTAL		0	
CLEANING			
PAINTING			
FREIGHT			
OTHER CHARGES SUBTOTAL			
MANAGER'S ADJUSTMENT CHARGE			
TOTAL COST		0	
TOTAL CHARGES		0	
ASSIGNED TRADE VALUE		0	USD
FINAL PRICE			USD
NOTES			

^ indicates the latest assigned trade value.